



Swimming Pool Official Inspection Report
 SISKIYOU COUNTY PUBLIC HEALTH
 & COMMUNITY DEVELOPMENT
 806 S. Main Street
 Yreka, California 96097
 ph: (530) 841-2100, fax (530) 841-4076

Facility Name: Mountain Fitness Wellness Center Spa CMHC# 607834

Address: 633 Lassen Ln, ML Shasta E-mail:

Permit Holder: Mountain Fitness Centers LLC Phone: 926-6010 Permit To Operate: Valid Not Valid

Chlorine / Bromine: 7.5 ppm pH: 7.4 Cyanurates: 0 ppm Pool Clarity: Clear

MAJ OUT COS The marked items represent Health Code violations and must be corrected as follows:

		The marked items represent Health Code violations and must be corrected as follows:		
		MAJ	OUT	COS
Pool Quality	1 Chlorine		X	X
	2 Bromine			
	3 pH			
	4 Cyanurates			
	5 Clarity			
	6 Test Kits			
	7 Cleanliness			
Safety Equipment	8 Rescue Pole			
	9 Life Rings			
	10 Safety Signs			
	11 Lifeguard			
	12 Lighting Elec.			
	13 Ladders			
	14 Depth Markers			
	15 Anti-Entrapment			
	16 Gates			
Construction	17 Pool Shell			
	18 Bottom & Sides			
	19 Decking & Coping			
	20 Diving Boards			
Recirculation Equipment	21 Filters			
	21 Pumps			
	23 Chlorinator			
	24 Flow Meter			
	25 Gauges			
	26 Skimmer & Gutters			
	27 Back Flow Preven.			
	28 Waste Water Preven.			
	29 Water Supply			
	30 Pipe & Fittings			
Restrooms	31 Showers			
	32 Toilet & Dressing			
	33 Ventilation			
Other	34 Responsible Person			
	35 General Sanitation			
	36 Daily Records			
	37 Storage			
	38 Miscellaneous			

Routine Inspection Conducted This Date.

1) Observed Chlorine @ .7 ppm. Maintain chlorine levels between 3-10 ppm. Corrected to 7.5 ppm during inspection.

MAJ = Major violation OUT = Out of compliance COS = Corrected on-site

Received By (Print): Zach Feil Received by (Signature): Zach Feil Date: 4-27-22

REHS (Print): Rich Florenco REHS (Signature): Rich Florenco Phone: 530-841-2114